


(上段) 手前側
(下段) 裏側

P9880U-210 BAF3145
P9880U-210 BAF3090

E10679 AA4081
E10679 AB1502

11=20 光学的検査 OK
LPV 300 ~ 700 Hz
後 170 Hz

型番	型番	gain (HV1200)	error	UTPM
MPPC S13360-1530CS 10573~10590				
PMT 11	BAF 3063	2.97E+07	0.102	AB0393
PMT 10	BAF 2866	1.91E+07	0.090	AB0426
PMT 11	BAF 3063	2.63691E+07		
PMT 10	BAF 3142	2.52E+07		
PMT 9	R9880U-210 BAF 2107	2.52E+07	0.102	E10679 AB1502



10:50
6/16